

Eric J. Holcomb Covernor

Kristina Box, MD, FACOG Stale Health Commissioner

November 19, 2018

RE: Lead Abatement Site Review

Unit.

\*\*\*Site Address\*\*\*\*

In compliance with the Indiana Administrative Code Title 410, Article 32, Lead-Based Paint Program, an on-site review was conducted on 11/19/2018 by the Indiana Lead and Healthy Homes Program at the property referenced above. The following lead-abatement violations were cited during the inspection,

Rule	Violation	Correction	
410 IAC 32-4-5(1)	Licensed Supervisor not on-site during the entire abatement project	Ensure Licensed Supervisor is on-site during the entire abatement project	
410 IAC 32-4-5(4)	Written occupant protection plan not on- site	Have written occupant protection plan on-site	
410 IAC 32-4-5(7)	Work area(s) not sealed off from non- work area(s)	Ensure work area(s) are sealed off from non-work area(s)	
410 IAC 32-4-5(8)	Plastic sheeting not being used directly below work site	Place plastic sheeting directly below work site.	
410 IAC 32-4-5(9)	Warning signs not posted at all entrances to work site	Post warning sign(s) at entrances	
410 IAC 32-4-5(10)	Access of non-workers limited from the work area	Limit access of non-workers from the work area	
410 IAC 32-4-5(12)	Exterior work area not restricted by barrier tape	Restrict exterior area with barrier tape	
410 IAC 32-4-5(13)	Daily clean-up of work area issue	Store lead-abated waste in an area inside the property line	
410 IAC 32-4-7(2)	Improper polyethylene sheeting used on carpeted floors	Cover with at least 2 layers of sheeting	
410 IAC 32-4-7(2)	Improper polyethylene sheeting used on carpeted floors	Use proper 6 mil polyethylene sheeting	
410 IAC 32-4-7(3)	Objects remaining in the work area not wrapped	Wrap remaining items with 6 mil plastic	
410 IAC 32-4-7(3)	Objects remaining in the work area not wrapped	Remove items from work area.	
410 IAC 32-4-7(4)	Area not sealed off from non-work areas	Seal off area with appropriate materials	
410 IAC 32-4-8	Improper exterior site preparation	Place 6 mil sheeting as close to foundation as possible extending beyond drip line	
410 IAC 32-4-11	Lead-based paint waste has not been disposed of properly	Lead hazard signs not displayed where waste is stored or the use of other security measures	





Eric J. Holcomb Gavernor

Kristina Box, MD, FACOG State Health Commissioner

		Warning label is not posted in areas where lead waste is stored
410 IAC 32-4-5(13)	Daily clean-up of work area issue	Remove/clean up visible paint chips on ground

To assure that additional lead hazards are avoided, you are hereby notified to correct all cited violations listed above. Failure to comply with this notice may result in further enforcement pursuant to IC 16-41-39.8. For questions or concerns about Lead Abatement Notifications and Monitoring please contact a member of the Indiana Lead and Healthy Homes Program staff at 317.233.1250.

Matthew Zampariello

Indiana State Dept of Health 100 N. SENATE AVE, N855

Indianappolis\_IN 46204

Phone: (999) 999-9999



## LEAD ABATEMENT INSPECTION DOCUMENTATION CHECK LIST

State Form 54358 (R / 11-10)	* Fail	Example *	☐ Initial Inspection☐ Re-inspection
Site Address:		Contractor:	Field Staff:
City:	_ State: IN	Contact Name:	Date: / /
ZIP Code:	_	Telephone Number:	Reason:

: % . ;		1 1. 9		Procedures for All Abatement Projects	
YES	NO	N/A	RULE	REQUIREMENT	CORRECTIVE ACTION
	図		410 IAC 32-4-5(1)	Is a licensed Supervisor on-site during the entire abatement project?	
X			410 IAC 32-4-5(3)	Has prior notification been submitted to ILHHP?	
	N		410 IAC 32-4-5(4)	is a written occupant protection plan on-site?	
			410 IAC 32-4-5(5)	Are any restricted practices being used?	☐ Stop open flame or torching ☐ Stop machine sanding or grinding or abrasive blasting without HEPA exhaust controls ☐ Stop dry scraping. Moisten before scraping. ☐ Operate heat gun at or below 1,100 degrees
		X	410 IAC 32-4-5(6)	is soil abatement being conducted properly?	Do not use abated soil as top soil Permanently cover the contaminated soil
	X		410 IAC 32-4-5(7)	Are work area(s) sealed off from non-work area(s)?	
		図		Are shoe covers being used?	Use shoe covers
	図		410 IAC 32-4-5(8)	Is plastic sheeting being used directly below work site?	Place plastic sheeting directly below work site
	Ø		410 IAC 32-4-5(9)	Are warning signs posted at all entrances to work site?	Post warning sign(s) at entrances Use correct warning sign language
X	П	П	410 IAC 32-4-5(10)	Is access of non-workers limited from the work area?	
		X	410 IAC 32-4-5(11)	Have chemically stripped surfaces been wet-cleaned?	
	A		410 IAG 32-4-5(12)	Is work area restricted by barrier tape?	Restrict exterior area with barrier tape Restrict interior area with barrier tape
			410 IAC 32-4-5(13)	Is required daily clean-up of work area occurring?	Store lead-abated waste in an area inside the property lined Lock lead-abated waste in containers, trucks, or trailers Use a HEPA filter for small debris Do not use dry sweeping methods Treat disposable supplies as waste



## LEAD ABATEMENT INSPECTION DOCUMENTATION CHECK LIST State Form 54358 (R / 11-10)

# F	711	EXAMPLE	X

Site Address:				Fleid Staff:	
City: S		Stat	e: IN Contact Name:	Date://	
ZIP Code:			Telephone Number:	Reason:	
0.3	4, 4.7	the Atlanta		Interior Lead Abatement Procedures	的。 医乳头体 经一个工作的
YES	NO	N/A	RULE	REQUIREMENT	CORECTIVE ACTION
			410 IAC 32-4-7(1)	Are warning signs posted at entrances and exits to work area?	Post warning sign(s) at entrance areas Post warning sign(s) at exits to work area
	X		410 IAC 32-4-7(2)	Is proper polyethylene sheeting used on carpeted floors?	Cover with at least 2 layers of sheeting Use proper 6 mil polyethylene sheeting Tape sheeting down with masking tape to wall or baseboard. Sheeting is torn/ripped cover with additional sheeting
図			410 IAC 32-4-7(3)	Are objects remaining in the work area wrapped?	Wrap remaining items with 6 mil plastic Remove items from work area.
			410 IAC 32-4-7(4)	Is area sealed off from non-work areas?	Seal off area with appropriate materials
			410 IAC 32-4-7(5)	Are floors covered with at least two layers of 6 mil plastic sheeting	Cover floors with required materials
			410 IAC 32-4-7(6)	Are HVAC systems shut off in the work area?	☐ Turn HVAC systems off ☐ Cover intake points with sheeting ☐ Cover exhausts points with sheeting
			410 IAC 32-4-7(7)	Has a passage through the common area erected?	No alternative entry or egress is located in common area. Erect a protected passage through the common area for safe passage.
			410 IAC 32-4-7(8)	Are posted work hours required for the common area? Are work hours posted in the common area?	Post and conduct abatement activities between established hours Clean work area with a HEPA vacuum at the end of each work day until area is clear of visible dust and debris.
				Exterior Abatement Procedures	
			410 IAC 32-4-8	Are proper EXTERIOR site preparations in place?	Contain water/abrasive blasting Place 6 mil sheeting as close to foundation as possible extending beyond drip line Raise sheeting to capture runoff liquid Use appropriate containers Tape seams Extend sheeting out from foundation a minimum of 5 feet and an additional 3 feet per floor Weight the sheeting at the foundation and along the edges and seams Erect vertical shrouds if wind exceeds 15 mph or if there is visible movement of debris
	IX		Lead 410 IAC 32-4-11	I-Based paint Abatement Disposal Proced  Has all lead-based paint waste been disposed of properly?	Waste not securely stored in a manner that prevents access  ☐ Material must be stored in locked containers, trucks, rooms, or trailers ☐ Lead hazard signs not displayed where waste is stored or the use of other security measures ☐ Warning label is not posted in areas where lead waste is stored

LEAD ABAT State Form 54358 (I	# YAIL EXAMPLE *	
Site Address:	Contractor: State: IN Contact Name:	Field Staff:
City:	State: IN Contact Name:	////
ZIP Code:	Telephone Number:	: Reason:
Notes/Comments		
- Licensea	l abatement supervisor no	of on site
- Written	co occupant protection plan	n not on site
- Proper	warning Signage and tap	be barriers not present.
1,000		Cri 1 1 1 holomond cit
	Not clear site is an	pe barriers not present. In official lead abatement sit
Į.		
- Proper	der work sites. Tarps	not Deing Used
\ \(\sigma\)	der work sites Tarns	are not acceptable
(A.2)	ou work sites. Tarps	are not acceptance.
_ /	the land of the	oved and laheled
Lead	waste improperly sta	Srea aria raiserea
	at nork site Wrap	lead waste in bmil
		1.1
	poly sheeting and la	bel appropriately as
	1. A waste Ramove	and clean area dil
	lead waste, nember	bel appropriately as and clean area daily.
FAIL		
11/	-	
		0 (1 )

Re-inspection will be done in following x days to ensure violations are corrected.

Lead Supervisor Signature:	ILHHP Representative Signature: